



POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION

SITE NUMBER

VII

MO-000010064

NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

A. SITE NAME

MARYVILLE COLLEGE

B. STREET (or other identifier)

13550 CONWAY RD.

C. CITY

ST. LOUIS

D. STATE

MO

E. ZIP CODE

63141

F. COUNTY NAME

ST. LOUIS

G. OWNER/OPERATOR (if known)

1. NAME

MARYVILLE COLLEGE

2. TELEPHONE NUMBER

314/434-4100

H. TYPE OF OWNERSHIP (if known)

☐ 1. FEDERAL☐ 2. STATE☐ 3. COUNTY☐ 4. MUNICIPAL☒ 5. PRIVATE☐ 6. UNKNOWN

I. SITE DESCRIPTION

MARYVILLE COLLEGE IS A PRIVATE SCHOOL OFF OF HWY. 40
OUTER ROAD ON CONWAY RD. DRUMS ARE IN WOODS ABOUT
1/4 MILE DOWN PATH ^{ORIGINATING} BETWEEN THE COR UNUM AND
RANCHHOUSE BUILDINGS ON CAMPUS.

J. HOW IDENTIFIED (i.e., citizen's complaints, OSHA citations, etc.)

CITIZENS COMPLAINT

K. DATE IDENTIFIED
(mo., day, & yr.)

11/6/80

L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM

CALLER FOUND SOME BARRELS ON THE PATH AND SAID
SOME HAD SOME CONTENTS. WE FOUND ABOUT 50 55-GALLON AND
30-GALLON DRUMS ON THE SIDE OF A LARGE CLEARING IN THE
TRAIL. ALL WERE EMPTY EXCEPT THOSE WHICH WERE OPEN AND
HAD CAUGHT SOME RAINWATER. WE TALKED WITH THE
PHYSICAL PLANT HEAD, BOB BROWN, AND HE SAID THE DRUMS
HAD ASPHALT SEALER IN THEM AND WERE NOW EMPTY. THEY
WERE BEING STORED THERE UNTIL HE EVENTUALLY SHIPS
THEM OFF TO A SALVAGE PLACE. NO FURTHER ACTION
IS NEEDED.

M. PREPARER INFORMATION

1. NAME

KEN GAMBARD

2. TELEPHONE NUMBER

314-849-1313

3. DATE (mo., day, & yr.)

11/7/80